

**PRODUCT CHANGE NOTICE**

**Notification Date:** 31st March 2011 **PCN #** FFC2A30-001

**Drawing Revision Letter:** B

**Product Identification**

FFC2A30-xx-x-x

**Effective from date code/batch code**

Immediately

**Description of Change**

Due to quality issue in soldering 47 to 60 positions have been removed from GCT drawing.

Product sidewalls are thin and during reflow higher circuit size (47+) insulator material is warping and causing contacts to raise up, this can cause shorting issues after FFC/FPC is plugged into the connector.

The issue does not effect right angle 0.5mm FFC connectors.

44 circuit part is now tooled.

**Reason for Change**

Quality risk above 47 circuits, see above.

**Anticipated impact on form, fit, function or reliability**

47 - 60 circuit versions are no longer available.

**Required inventory action**

None

**Contact Information**

If there are any questions, comments or suggestions regarding this PCN please contact GCT.

Global Connector Technology HK Limited  
155-157 King's Road  
North Point,  
Hong Kong, PRC

Tel: +852 2578 9030  
Fax: +852 2578 9000

[E-mail: sales@gct-apac.com](mailto:sales@gct-apac.com)

Global Connector Technology, Inc  
3 Industrial Park Road,  
Medway, MA 02053  
USA

Tel: +1 877-424-7899 (Toll Free)  
Tel: +1 508-570-2438 (Local)  
Fax: +1 508-796-6162

[E-mail: sales@gct-americas.com](mailto:sales@gct-americas.com)

[www.globalconnectortechnology.com](http://www.globalconnectortechnology.com)

Global Connector Technology UK Limited  
7 Sutherland Court, Brownfields,  
Welwyn Garden City, Hertfordshire,  
AL7 1BJ,  
United Kingdom

Tel: +44 (0)1707 321122  
Fax: +44 (0)1707 321121

[E-mail: sales@gct-europe.com](mailto:sales@gct-europe.com)